



Consider that some of the cables attached to these connectors might be mirrored.

If you are not sure about the orientation make sure to measure VDD before attaching to a board or programming tool.